

TASK NO.	TASK/DESCRIPTION	NOTES
H4.09	<p data-bbox="485 360 1150 383">H4 EXTERNAL DOORS, OPENINGS AND HATCHES</p> <p data-bbox="411 421 799 450">Door Locking Arrangements</p>  <p data-bbox="411 1442 1217 1570">Upper deck door locking arrangements are seized in numerous locations. Contractor is to free up /RENEW hasp and staple fittings on all associated doors as required. REPRESENTATION on completion. ALLOW for 7m² REPRESENTATION. ALLOW for 23 doors.</p>	<p data-bbox="1251 450 1450 613">Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p data-bbox="1251 647 1450 757">IAW Paint scheme -General 12 and Annex B refer.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H5.04	<p data-bbox="539 322 1070 349">H5 TOPSIDES AND SUPERSTRUCTURE</p> <p data-bbox="403 385 608 416">Draught Marks</p>  <p data-bbox="403 1037 1214 1155">Fwd, Midships and Aft draught marks port and stbd are obscured with marine growth and paint coverings are degraded. All relevant areas to be cleaned and REPRESENTED (Black on topsides, white on boot toppings).</p> <p data-bbox="403 1167 831 1193">ALLOW for 6m² REPRESENTATION.</p>	<p data-bbox="1249 385 1444 495">IAW Paint scheme -General 12 and Annex B refer.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
	H5 TOPSIDES AND SUPERSTRUCTURE	
H5.03	<p data-bbox="405 383 863 416">Oil Rig Training Aid Fixing Points</p>  <p data-bbox="405 813 1214 954">The oil rig training aid affixed port side outboard has 4 welded fixing points. These have all had a total breakdown of paint coatings and are showing signs of active corrosion. Fixing points to be SURVEYED and remedial action taken as required. All areas to be REPRESENTED on completion.</p> <p data-bbox="405 967 834 996">ALLOW for 4m² REPRESENTATION.</p>	<p data-bbox="1249 387 1445 501">IAW Paint scheme -General 12 and Annex B refer.</p> <p data-bbox="1249 533 1445 613">To be completed in conjunction with H5.06.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H5.05	<p data-bbox="539 324 1070 353">H5 TOPSIDES AND SUPERSTRUCTURE</p> <p data-bbox="400 387 655 416">Draught Indicators</p> <div data-bbox="397 432 1171 759">  </div> <p data-bbox="400 775 1209 875">Port and stbd draught indicators are obscured, worn and difficult to identify. Indicators (2 x port, 2 x stbd) – REPRESENTATIVE coatings. ALLOW for 8m² REPRESENTATION.</p>	<p data-bbox="1249 387 1444 499">IAW Paint scheme -General 12 and Annex B refer.</p>

