

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: F6 DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (north) – 2040x1620. 2. Louvre (north) – 670x1850. 3. X2 openings with metal work still present (see photo). Opening in the metal work measured – 800x940. 4. Door (south) – 2040x1610. 5. Louvre (south) – 700x1185.	• Access restricted due to vegetation. • Partially cleared of vegetation. • Metal work present in building.



Door; Louvre (south).

Door; Louvre (north).

Access.

Openings with metal work (east). All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: K3 DATE: 17/06/2024	LOCATION:
MEASUREMENTS: 1. Door (north) – 1980x1670. 2. X4 windows (west) – 920x1720.	NOTES: • Cleared of vegetation. • Access restricted due to rough/wet ground and vegetation.



Door (north).
All photos are ©Natural England.

Windows (west).

Access.


HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: K4 DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Window (annex) (north) – 1060x1320. 2. X5 windows (north) – 2120x1330. 3. Window (west) – 2100x1330. 4. X2 windows (west) – 1400x1820. 5. Door (annex) (south) – 2900&2200x2990. 6. Knocked through windows (south) – 2900x4650. 7. X3 windows (south) – 1400x1820. 8. Door (annex) (east) – 2050x1050.	• Access restricted due to vegetation. • Partial clearance of vegetation.



Windows (south).
Openings (south)



Windows (north).



Windows (west).

All photos are ©Natural England.

BUILDING ID: LATRINE 28 DATE: 17/06/2024	LOCATION: locate.dress.danger
MEASUREMENTS: 1. Door (west) – 2020x840. 2. X2 window (west) – 620x620. 3. Window (east) – 630x1240.	NOTES: • Restricted access due to vegetation.




Door; Windows (west).
All photos are ©Natural England.

Window (east).

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: N5 DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Not measured due to flooding.	• Not cleared of vegetation. • Not accessible due to vegetation and water levels. • Barn owls present.



N5 Flooded.
 All photos are ©Natural England.

Access.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: N7 DATE: 17/06/2024	LOCATION: stages.oddly.finest
MEASUREMENTS:	NOTES:
1. X3 windows (glazed) (north) – 500x1610. 2. Door (west) – 2140x1220. 3. Louvre (west) – 765x1590. 4. X4 circular openings (south) – 460 diameter. 5. Door (east) – 2140x1220. 6. Louvre (east) – 765x1590.	• Mostly cleared of vegetation. • Access restricted due to vegetation. • Scrap metal present.



Door; Louvre (east).
Circular openings (south). All photos are ©Natural England.

Windows (glazed) (north).

Access.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: M2 DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (north) - 2770x2460. 2. Lower hole (north) - 250x460. 3. X4 window openings (west) - 1010x1780. 4. X1 window opening (south) - 1010x1780. 5. X2 louvre (north)(south) - ~ 670x1260. 6. Distance between external pillars (west) from N to S: 6.1. – 1940. 6.2. – 1890. 6.3. – 1890. 6.4. – 1950. 7. Distance between external pillars (south) – 2480.	• Mostly cleared of vegetation. • Access restricted due to single windblown tree. • Obvious signs of previous public usage. • Large amounts of detritus.



Door; Louvre; Holes (north). Holes (north). Louvre (south).
Window openings (west)(south). All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: M3 DATE: 17/06/2024	LOCATION:
MEASUREMENTS: 1. Door (north) – 1980x1670. 2. X4 windows (west) – 920x1720.	NOTES: • Restricted access due to vegetation.



Door (north).
All photos are ©Natural England.

Windows (west).

Access.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: S17 DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (west) – 2210x1070.	• Clear of vegetation. • Access clear. • Previous door shuttering removed. • Barn owls present.



Door opening (west). Barn owl entrance.
 All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: S18 DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (west) – 2230x1070.	• Clear of vegetation. • Access clear.



Door (west).
All photos are ©Natural England.

BUILDING ID: S19 DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (west) – unmeasured due to vegetation (appears standard).	• Not cleared of vegetation. • Not accessible. • Presumed un-swept? • Barn owls present.



Access. Door (west).
All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: S21 DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door opening (west) – 2220x1060.	• Mostly cleared of vegetation. • Access restricted due to vegetation. • Previous door shuttering removed.



Door opening (west).
All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: M6 (ANNEX) DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1.	• Restricted access due to vegetation.



All photos are ©Natural England.

BUILDING ID: M7 (ANNEX) DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1.	• Inaccessible due to vegetation. • Similar building type to M6

BUILDING ID: N3 (ANNEX) DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Window (north) – 1010x1310. 2. Door (west) - 2230x1650. 3. Door (west) – 2210x1650 4. Door (south) – 3000&2310x2920. 5. Door (east) – 2000x1040.	• Restricted access due to vegetation and flooding.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: N4 (ANNEX) DATE: 17/06/2024	LOCATION:
MEASUREMENTS: 1. Window (north) – 1010x1320. 2. Door (west) – 2250x1640. 3. Door (west) – 2250x1650. 4. Door (partially obstructed) (south) – 3060&2250x2900. 5. Door (east) – 2050x1040.	NOTES: Access restricted due to vegetation and flooding.

Summary: 76 no. in Total

Building	Opening	Size (mm)
F6	Door	2040 x 1620
F6	Louvre	670 x 1850
F6	Opening	800 x 940
F6	Opening	800 x 940
F6	Door	2040 x 1610
F6	Louvre	700 x 1185
K3	Door	1980 x 1670
K3	Window	920 x 1720
K3	Window	920 x 1720
K3	Window	920 x 1720
K3	Window	920 x 1720
K4	Window	1060 x 1320
K4	Window	2120 x 1330
K4	Window	2120 x 1330
K4	Window	2120 x 1330
K4	Window	2120 x 1330
K4	Window	2120 x 1330
K4	Window	2100 x 1330
K4	Window	1400 x 1820
K4	Window	1400 x 1820
K4	Door	2900 x 2200
K4	Window	2900 x 4650
K4	Window	1400 x 1820
K4	Window	1400 x 1820
K4	Window	1400 x 1820
K4	Door	2050 x 1050
Latrine 28	Door	2020 x 840
Latrine 28	Window	620 x 620
Latrine 28	Window	620 x 620

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

Latrine 28	Window	630 x 1240
N7	Window	500 x 1610
N7	Window	500 x 1610
N7	Window	500 x 1610
N7	Door	2140 x 1220
N7	Louvre	765 x 1590
N7	Circular Opening	460 dia
N7	Circular Opening	460 dia
N7	Circular Opening	460 dia
N7	Circular Opening	460 dia
N7	Door	2140 x 1220
N7	Louvre	765 x 1590
M2	Door	2770 x 2460
M2	Hole	250 x 460
M2	Window	1010 x 1780
M2	Window	1010 x 1780
M2	Window	1010 x 1780
M2	Window	1010 x 1780
M2	Window	1010 x 1780
M2	Louvre	670 x 1260
M2	Louvre	670 x 1260
M2	Pillar Gap	1940
M2	Pillar Gap	1890
M2	Pillar Gap	1890

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

M2	Pillar Gap	1950
M2	Pillar Gap	2480
M3	Door	1980 x 1670
M3	Window	920 x 1720
M3	Window	920 x 1720
M3	Window	920 x 1720
M3	Window	920 x 1720
S17	Door	2210 x 1070
S18	Door	2230 x 1070
S19	Door	Unmeasured
S21	Door	2220 x 1060
E6	Arch	5500 x 10320
E6	Wall	1560
N3	Window	1010 x 1310
N3	Door	2230 x 1650
N3	Door	2210 x 1650
N3	Door	3000 x 2310
N3	Door	2000 x 1040
N4	Window	1010 x 1320
N4	Door	2250 x 1640
N4	Door	2250 x 1650
N4	Door	3060 x 2250
N4	Door	2050 x 1040