

WHITCHURCH TOWN HALL RE-ROOFING WORKS PHOTOGRAPHS


These photographs are intended to assist in pricing the work, but please note they have been taken over the past 8 years; we cannot guarantee the current condition.



Front, east elevation



Rear, west elevation



Cupola dome



Cupola flat roof base



cupola base and cladding to pediment and into gutters either side



parapet gutter and other details



end of lead lined timber gutter where overflow to be fitted.