










1. DRAWING SUPPLIED BY CLIENT.
2. DRAINAGE INFORMATION HAS BEEN DETERMINED WITHOUT MAN ENTRY INTO CHAMBERS AND WHILST EVERY EFFORT HAS BEEN MADE TO CORRECTLY IDENTIFY THIS INFORMATION, IT SHOULD ALWAYS BE CHECKED IN AREAS THAT ARE CRITICAL TO THE FUTURE PROPOSAL.
3. ALL SEWERS ARE PRESUMED TO BE STRAIGHT BETWEEN CHAMBERS.
4. UNABLE TO TRACE ALL GAS & WATER, DUE TO BEING PLASTIC.

Key (Utilities)

	ELECTRICITY CABLE
	HIGH VOLTAGE CABLE
	OVERHEAD ELECTRIC LINES
	THREE/4" LIGHT SIGNAL
	BT CABLES
	TELEPHONE CABLE
	CCTV / CABLE TELEVISION
	FIBRE OPTICS
	OVERHEAD TELECOM LINES
	SURFACE WATER DRAINAGE
	FOX WATER DRAINAGE
	COMBINED DRAINAGE
	WATER SUPPLY PIPE
	GAS PIPE
	WATER SUPPLY PIPE
	HEATING MAIN
	EMPTY DUCT
	FUEL LINE - PETROL
	FUEL LINE - DIESEL LPG
	OFF-SET FILL
	VENT PIPE
	GAUGE LINE
	GROUND PENETRATING RADAR
	UNIDENTIFIED
	EARTH CABLE
	SURVEY BOUNDARY
	LARGE DRAINAGE
	END OF TRACE
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	
	

Rev	Date	Description	Drawn
-----	------	-------------	-------

Diagnostic and/or Ground Penetrating Radar techniques have been used to locate underground utilities and to draw the Geotechnical Engineering Ltd (GEL) has made every endeavour to make sure the information contained in this report is accurate and of the highest quality. GEL has used any recent drawings provided by the client or by the State Providers, at the client's request, at the time of the survey. Any information taken from these drawings (e.g. pipe size and depth) is not for liability purposes. GEL does not warrant the accuracy of the information contained in these drawings. GEL is not liable for any topographical survey data that has not been undertaken by us. Any inaccuracies relating to topographical/ground plane/Drainage data that we have no control over is the liability of the customer. Where open areas are shown on the drawings, they are not intended to be a representation of the ground surface, but cannot be as depths shown are drains are usually to invert (base of drainage channel) unless otherwise stated.

At GEL we use skilled staff and modern, calibrated equipment to perform our surveys. However, the completion of any survey is dependent on the weather and the availability of the client's personnel. The completion of a service/feature is of particular importance to a project where it is strongly advised that discussions are held with GEL, regarding possible limitations or anomalies. It is also strongly advised that full excavations should be undertaken to confirm survey data. GEL is not responsible for any damage to property or persons caused by the use of the equipment or the information provided.

[illegible]

Lake District National Park Author

Brockhole Visitor Centre
Windermere LA23 1LJ

Scale 1:500	Sheet Size: A0	Sheet Number: 1	Date: 10/01/11
Project Number: 32603	Rev: -	Surveyed By: RT	Approved By: G170

