Frequency inspection

Ref. No.	Inspection Name	No. locations	(mths)	2026/27	2027/28	2028/29
	ELECTRICAL					
E001	Electrical Installation Condition Report	16		1	4	9
E002	Portable Appliance Testing	14		14	14	14
E003	Emergency Lighting Servicing	6		6	6	6
E004	Lightning Conductor Rod Servicing	7		7	7	7
	TOTA	L		28	31	36
	WATER					
W001	Water/Air Heating System Servicing	1		1	1	1
W002	Septic Tank Servicing	1		1	1	1
W003	Water Well Treatment	1		1	1	1
W004	Mains Water Filter Change	2		4	4	4
W005	Rainwater Harvesting Tank Servicing	1		1	1	1
	TOTA	L		8	8	8
	GAS					
G001	Gas Safety Record (Boiler Servicing)	5		5	5	5
	ТОТА	L		5	5	5
	FIRE					
F001	Fire Extinguisher Servicing	15		15	15	15
F002	Fire Alarm Servicing	7		7	7	7
F003	Fire Risk Assessment	16		1	5	12
F004	Diesel Tank Servicing	1		1	1	1
F005	Petrol Tank Servicing	1		1	1	1
F006	Chimney Sweep	. 1		1	1	1
	TOTA	L		26	30	37
0004	SECURITY Consists of					
S001	Intruder Alarm Servicing	8		8	8	8
S002	CCTV Servicing	4		4	4	4
S003	Roller Shutter Door Servicing	10		10	10	10
S004	Alarm Monitoring Services	5		5	5	5
	TOTA EQUIPMENT	L		27	27	27
E0001	· ·	11		11	11	11
EQ001 EQ002	LOLER/PSSR Annual Inspection LOLER/PSSR Bi-annual Inspection			11		
EQ002 EQ003	Forklift Servicing	4		8	8 1	8
EQUUS	TOTA	1		1 20	20	1 20
	ASBESTOS	_		20	20	20
A001	Asbestos Survey	3		3	0	0
,1001	TOTA			3	0	0
	EXTERNAL HIGH LEVEL CLEANING	-		<u> </u>		.
C001	Cleaning - roof & guttering	1		1	1	1
0001	Oteaning - 1001 & guttering	1		•	-	-

Total No. req'd

for whole

for whole	
contract	Notes
14	two not due under this contract
42	home offices and properties not due under this contract;
18	
21	
3	
3	
3	
12	2 locations require 2 visits per annum = 4 total
3	2 to sation or oquino 2 violes por armam - restat
3	
15	
45	
21	battery operated wireless units
18	
	1 location requires annual assessment
3	
3	
3	
24	
12	
30	
15	
33	
24	4 locations require 2 visits per annum = 8 total
3	γ
J	
3	
3	
_	
3	