

ASBESTOS MANAGEMENT POLICY AND PLAN

EMPLOYER	Royal Institution of Cornwall	
COMPANY TRADING NAME	Royal Cornwall Museum	
MAIN CONTACT PERSON	John Negus	
ADDRESS OF WORKPLACE	25 River Street, Truro, Cornwall, TR1 2SJ	
DATE OF PREPARATION	10 April 2011	
NAME OF ADVISER	Terry Pike	<i>Health & Safety Adviser Safety Cornwall Ltd</i>
REFERENCE	TE04/TP/	<i>Safety Cornwall Ltd Client Reference Number</i>



6 Glenthorne House
Truro Business Park
Threemilestone
Truro
TR1 6BW

(01872) 242207 / 278053

enquiries@safetycornwall.co.uk

www.safetycornwall.co.uk

THIS DOCUMENT IS COPYRIGHT

Royal Cornwall Museum	Asbestos management plan	Date compiled: April 2011
-----------------------	--------------------------	---------------------------

© This document is copyright and remains the intellectual property of Safety Cornwall Ltd

ASBESTOS MANAGEMENT POLICY AND PLAN

ASBESTOS MANAGMENT POLICY OVERVIEW

This asbestos policy document is designed to meet the **legal requirements** of the Health & Safety at Work Etc Act 1974 and The Control of Asbestos Regulations 2006.

This policy document contains relevant **mandatory** and procedural items, including in particular:

1. a signed undertaking by the Director and the Chair of the Trustees who are responsible for the approval of all RCM policies
2. A signed undertaking from the person responsible for administering and managing asbestos containing materials (ACMs) within the RCM's control.
3. A strategy for managing ACMs within the RCM's control whether identified by survey or presumed to exist.
4. Procedures for communicating the arrangements for managing ACM to employees, contractors or maintenance workers who's health or wellbeing may be affected by the possible release of asbestos fibres.

The signed undertaking is a **commitment in law** that the RCM will implement the contents of the asbestos policy document and management plan. The employer may be held to account in law if the company fails to manage health and safety accordingly.

The asbestos management policy and plan must be reviewed and revised, as often as may be appropriate: e.g. this should take place at least annually or at any time when there is planned to be any work, alterations or maintenance which has the potential to disturb asbestos containing materials.

This policy document must be **brought to the attention of all employees, contractors about to be engaged in refurbishment work or maintenance workers about to be engaged in maintenance work.**

ASBESTOS MANAGEMENT POLICY AND PLAN

STATEMENT OF POLICY

It is the policy of the Royal Cornwall Museum to ensure, so far as is reasonably practicable, that risks to health from the release of asbestos fibres are eliminated.

The Royal Cornwall Museum is to engage the services of a competent person or persons to:-

- Survey and sample for asbestos containing materials
- Identify asbestos containing materials held as exhibits
- Assess the condition of any known asbestos containing materials
- Record the location of any known asbestos containing materials or presumed ACMs
- Assess the potential risk of the release of asbestos fibres
- Remove any ACMs which are at risk of releasing fibres, contained within the building fabric, if reasonably practicable to do so
- Append a copy of the current asbestos survey and location drawings to the asbestos policy / management plan
- Inform workers and employees of the consequences to health from exposure to asbestos fibres

Signed:	Dated:
Name:	
The Director responsible for the approval of all RCM policies	

Signed:	Dated:
Name:	
The Chair of the Trustees responsible for the approval of all RCM policies	

Royal Cornwall Museum	Asbestos management plan	Date compiled: April 2011
-----------------------	--------------------------	---------------------------

ASBESTOS MANAGEMENT POLICY AND PLAN

PROCEDURES

ASBESTOS REGISTER

- The findings of the asbestos survey and details of any exhibits containing asbestos are to be recorded in an asbestos register for the property.
- The Operations Manager is to ensure that an up to date asbestos register / survey is available at all times. All Heads of Departments are to ensure that their staff members are informed of the location and presence of the asbestos policy.
- Drawings and plans of the building are to be 'marked up' to show the location of asbestos containing materials. All marked up drawings/plans are to be included in the Asbestos Register.
- The Asbestos Register is to contain an overall risk rating for each object containing asbestos or presumed to contain asbestos. The risk from the asbestos containing materials is to be classified as follows:

High: Materials which contain asbestos and are in a condition and/or location which necessitates urgent remedial action. These materials are not normally suitable for containment and removal will normally be required.

Medium: Materials which contain asbestos and are in a condition and/or location where some remedial action is required. These materials may be suitable for containment e.g. encapsulation but removal in the long-term may be appropriate.

Low: Materials which contain asbestos but are in a condition and/or location which does not give rise to a significant health risk provided it remains undisturbed or undamaged by routine maintenance of regular work activities.

Trivial: This material does not pose a risk under normal conditions provided it is not finely abraded. When this material is removed, it should be removed without cutting or abrading and disposed of as special waste.

The "Risk Rating" is the risk to the normal users of the property based on the material type, its condition and location, whether it is vulnerable to damage and whether it has been protected or not. This risk assessment is to be updated every time the property or asbestos containing materials are re-inspected.

Maintenance, repair, installation, alteration or refurbishment works are subject to the **Construction Design and Management Regulations 2007**. Directors and Heads of Department are to inform contractors of the location of the asbestos register.

ASBESTOS MANAGEMENT POLICY AND PLAN

MARKING OF ASBESTOS CONTAINING MATERIALS

The Operations Manager is to ensure that all asbestos containing material is labelled in accordance with the Health and Safety (Safety Signs and Signals) Regulations 1996 **unless it is in a public area**. The relevant sign to be used is as follows:



With the following notice if the sign is situated on the asbestos containing material
WARNING – ASBESTOS CONTAINING MATERIAL

Or with the following notice if the sign is situated at the entrance to an area in which asbestos containing material is located

**WARNING – AREA CONTAINS ASBESTOS CONTAINING MATERIALS;
SEE ASBESTOS REGISTER FOR FURTHER DETAILS**

EXHIBITS AND OBJECTS

Whilst the Operations Department is responsible for the management of asbestos within the building fabric, fixtures and fittings and services, the Collections Manager is responsible for the management of exhibits and objects containing asbestos.

Signed:	Dated:
Name: John Negus Operations Manager	
The Responsible Person for asbestos policy / management on behalf of the RCM	

Signed:	Dated:
Name: Sara Chambers Collections Manager	
The Responsible Person for asbestos policy / management on behalf of the RCM	

Royal Cornwall Museum	Asbestos management plan	Date compiled: April 2011
-----------------------	--------------------------	---------------------------

ASBESTOS REGISTER

ASBESTOS ACTION PLAN FOR KNOWN OR PRESUMED ASBESTOS CONTAINING MATERIALS

The following tables identify any sampled or presumed asbestos as noted in the type 2 survey.

The exposure risk is the estimated risk of exposure to asbestos fibres, released by the material identified as or presumed to contain asbestos, for staff and the general public using the Museum premises.

The person responsible for the administration of the Asbestos Management Plan will make the details of any presumed asbestos containing materials known to any company or worker carrying out maintenance or refurbishment to these areas. If any work is planned which could potentially disturb materials which may contain asbestos, suspected ACM will be subject to a Demolition / refurbishment asbestos survey, this information is to be passed to any company or worker likely to be carrying out this work The Control of Asbestos Regulations 2006.

Room No./description	Sample Ref. No:	Location	Asbestos Type	Product Type	Condition	Exposure risk	Further action required
Level 1, safe room	P1	Presumed AIB within doors	Presumed Amosite & Chrysotile	Presumed Asbestos insulation board	Unknown Encapsulated	Low	No immediate action required. Eventual removal no time limit on this action
Level 1, safe room	P2	Presumed AIB within doors	Presumed Amosite & Chrysotile	Presumed Asbestos insulation board	Unknown Encapsulated	Low	No immediate action required. Eventual removal, no time limit on this action
Level 1, Bookshop office	P1	Presumed AIB within doors	Presumed Amosite & Chrysotile	Presumed Asbestos insulation board	Unknown Encapsulated	Low	No immediate action required. Eventual removal, no time limit on this action.
Level 3, De-Pass Gallery	5107/02	Low level panel covering pipe duct	Chrysotile	Asbestos cement	Good Decorated over	Low	Believed to have been removed and replaced with plywood. Establish status of material and remove if still present.

ASBESTOS REGISTER

Room No./description	Sample Ref. No:	Location	Asbestos Type	Product Type	Condition	Exposure risk	Further action required
Level 4, room above lift 2	P1	Presumed flash guards within electrical switch gear	Presumed Chrysotile	Presumed asbestos textile	Unknown Encapsulated	Low	No further action necessary at this time. Flash guards to be removed or replaced if electrical upgrade is required in the future.
Level 4, room above lift 2	P2	Presumed lift motor pads	Presumed Chrysotile	Presumed asbestos cement	Unknown	Low	No further action necessary at this time. Lift motor pads to be replaced as identified during lift maintenance procedures. Time limit to be established by lift engineers.
External	P	Presumed roof tiles over the front library area	Presumed Chrysotile	Presumed asbestos cement	Good	Low	No further action necessary at this time.
Hairdressers next to museum. External	P	Presumed roof tiles	Presumed Chrysotile	Presumed asbestos cement	Good	Low	The hairdresser's shop has been disposed and is no longer under the control of the museum. No further action necessary.

Royal Cornwall Museum

Asbestos management plan

Date compiled: April 2011

© This document is copyright and remains the intellectual property of Safety Cornwall Ltd

ASBESTOS REGISTER

ASBESTOS ACTION PLAN FOR INACCESSIBLE AREAS

The following areas have not been examined for the presence of asbestos containing materials and therefore have, for the purpose of the Asbestos Management Plan, been presumed to contain asbestos.

The person responsible for the administration of the Asbestos Management Plan will make the details of any areas not tested for the presence of asbestos containing materials known to any company or worker carrying out maintenance or refurbishment to these areas.

Should any work be planned which could potentially disturb materials which may contain asbestos, the affected materials or areas will be subject to a Demolition / refurbishment asbestos survey, this information is to be passed to any company or worker likely to be carrying out this work, prior to the commencement of the work.

Room No./description	Details of access	condition	Further action required
Access was not gained to ceiling voids where ceilings are fixed	within partition or behind clad walls	Unknown Encapsulated	No further action required at this time.
Level 1 Store	no access within safe	Unknown Encapsulated	No further action required. Eventual removal no time limit on this action.
Level 1 Safe Room	no access within safe	Unknown Encapsulated	No further action required. Eventual removal no time limit on this action.
Level 1 Bookshop office	no access to fireplace	Unknown Encapsulated	No further action required at this time.
Level 1 Workshop 1	no access to under floor ducting	Unknown Encapsulated	No further action required at this time.
Level 2 Middle Store	limited access due to storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Level 2 Store	limited access due to storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.

It must be assumed that all inaccessible areas contain ACMs until proven otherwise.

Royal Cornwall Museum	Asbestos management plan	Date compiled: April 2011
-----------------------	--------------------------	---------------------------

© This document is copyright and remains the intellectual property of Safety Cornwall Ltd

ASBESTOS REGISTER

Room No./description	Details of access	condition	Further action required
Level 3 Gallery	ceiling too high to access	Unknown inaccessible	No further action required at this time. Establish the presence of ACM prior to work to being carried out on this element.
Level 3 Archive Store	limited access behind storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Level 3 Archive Store	limited access behind storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Level 3 Philbrick Room	ceiling too high to access	Unknown inaccessible	No further action required at this time. Establish the presence of ACM prior to work to being carried out on this element.
Level 3 Office 2	no access behind wood units to chimney	Unknown Encapsulated	No further action required at this time. Establish the presence of ACM prior to work to being carried out on this element.
Level 3 Store 1	limited access due to storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Level 3 Store 2	limited access due to storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Level 3 Trefry Gallery	ceiling too high to access	Unknown inaccessible	No further action required at this time. Establish the presence of ACM prior to work to being carried out on this element.
Level 3 Art Store 1	limited access behind storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Level 3 Art Store 2	limited access behind storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.
Basement Store	limited access due to storage	Unknown inaccessible	No further action. Establish presence of ACM if stored materials are removed.

It must be assumed that all inaccessible areas contain ACMs until proven otherwise.

Royal Cornwall Museum

Asbestos management plan

Date compiled: April 2011

© This document is copyright and remains the intellectual property of Safety Cornwall Ltd

.....

Figure 1 is a line graph with the x-axis labeled 'Days since start of study' ranging from 0 to 10. The y-axis is also labeled 'Days since start of study' and ranges from 0 to 10. The data points are plotted at intervals of 1 day, showing a curve that starts at (0,0) and increases, leveling off around day 10.

Royal Cornwall Museum	Asbestos management plan	Date compiled: April 2011
-----------------------	--------------------------	---------------------------

© This document is copyright and remains the intellectual property of Safety Cornwall Ltd

ASBESTOS REGISTER

EXTRACT FROM TYPE 2 SURVEY

Table 1: Asbestos Containing Materials (including presumed materials not sampled)

Room No./Description	Sample Ref. No:	Material Location	Approx. Quantity (m ²)	Asbestos Type	Product Type	Material Assessment Score	Accessibility	Comments
Level 1, Safe Room	P1	Presumed AIB within doors	-	Presumed Amosite & Chrysotile	Presumed Asbestos Insulation Board	-	Low	
Level 1, Safe Room	P2	Presumed AIB within safe linings	-	Presumed Amosite & Chrysotile	Presumed Asbestos Insulation Board	-	Low	
Level 1, Bookshop Office	P1	Presumed AIB within safe linings	-	Presumed Amosite & Chrysotile	Presumed Asbestos Insulation Board	-	Low	
Level 3, De-Pass	5107/02	Low level panel covering pipe duct	0.25	Chrysotile	Asbestos Cement	3	High	
Level 4, Room above Lift 2	P1	Presumed flash guards within electrical switch gear	-	Presumed Chrysotile	Presumed Asbestos Textile	-	Low	
Level 4, Room above Lift 2	P2	Presumed lift motor pads	-	Presumed Chrysotile	Presumed asbestos Cement	-	Low	
External	P	Presumed roof tiles over front library area	-	Presumed Chrysotile	Presumed Asbestos Cement	-	Low	
Hairdressers next to museum, External	P	Presumed roof tiles	-	Presumed Chrysotile	Presumed Asbestos Cement	-	Low	

KEY: P = PRESUMED; SP = STRONGLY PRESUMED. Accessibility - low, medium or high based on surveyors opinion. For further information relating to material assessment score, refer to appendix E.

ASBESTOS REGISTER


EXTRACT FROM TYPE 2 SURVEY

Table 2: Suspect Asbestos Containing Materials found not to contain asbestos

Room No. / Description	Sample Ref. No.	Material Location	Asbestos type	Product Type	Comments
Level 2, Stairwell outside offices	4859/01	Stair nosing	Asbestos Not Detected	Stair nosing	Also found in: Level 2, Storage only room Level 2, Upstairs workshop area
Level 2, Area outside rear store/stairwell	4859/02	Stair nosing	Asbestos Not Detected	Stair nosing	
Level 3, De-Pass	5107/01	Walls & ceiling to plant room	Asbestos Not Detected	Cement	Also found in: Plant room
Level 3, Courtney Library, lower level	5107/03	Green lino	Asbestos Not Detected	Vinyl floor covering	
Level 3, Store 2	5107/04	Under sink	Asbestos Not Detected	Sink pad	
Hairdressers next to museum, Back room	4780/01	Ceiling	Asbestos Not Detected	Textured coating	Also found in: Hairdressers, 1 st Room

BASEMENT LAYOUT / PLAN

Royal Cornwall Museum
Basement



PRESUMED ASBESTOS CONTAINING MATERIALS
FOUND TO EXTERNALS

© This drawing is Copyright. It should not be relied on or used in circumstances other than those for which it was prepared. The user of this drawing is advised that the Council accepts no responsibility for this drawing to any person other than the person(s) to whom it was commissioned.

N KEY FOR THE IDENTIFICATION OF PLANS

Presumed / Possible asbestos containing materials found in room



REF	DATE	NATURE OF REVISION
0	21/05/08	ORIGINAL

REVISIONS



CORNWALL COUNCIL
RICHARD FRENCH
DIRECTOR
PLANNING, TRANSPORTATION AND ESTATES
CORNWALL COUNCIL
CORNWALL TR1 3AY
The Design and Maintenance Consultancy

LOCATION

Royal Cornwall Museum
Basement

PROJECT
TYPE 2 ASBESTOS SURVEY

PAGE NUMBER

PAGE 1 OF 7

PROJECT MANAGER

P. LEBURN

SCALE

Not to Scale

DRAWING NO


75285

REVISION

R0

LEVEL 1 LAYOUT / PLAN

**Royal Cornwall Museum
Level 1**



PRESUMED ASBESTOS CONTAINING MATERIALS FOUND TO EXTERNALS

* SEE REPORT APPENDED

© This drawing is Copyright. It should not be relied on or used in circumstances other than those for which it was originally prepared and for which Cornwall County Council was originally commissioned. Cornwall County Council accepts no responsibility for this drawing to any party other than the person(s) by whom it was commissioned.

KEY FOR THE INTERPRETATION OF PLANTS

Room	Presumed / possible asbestos containing materials found in room
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
160	
161	
162	
163	
164	
165	
166	
167	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	
199	
200	

REV	DATE	NATURE OF REVISION
0	20/05/08	ORIGINAL



DIRECTOR
PLANNING, TRANSPORTATION and ESTATES
County Hall, Turo
Cornwall TR1 3AY
The Office and Maintenance Consultant

Royal Cornwall Museum
Level 1

TYPE 2 ASBESTOS SURVEY

RESEARCH DESIGN

PAGE 2 OF 7

PROJECT MANAGER	C. Stephen
EXECUTOR	P. Leban

SCALE

Not to Scale

75285	R0
-------	----

LEVEL 2 LAYOUT / PLAN

Floor plan of the first floor of a building. The plan shows a large central area labeled 'MAIN GALLERY'. To the left of the main gallery is a 'RASHLEIGH' area. To the right of the main gallery is a 'BONYTHON' area. Further right is a 'MIDDLE STORE'. Above the middle store is a 'CAFE' and a 'CAFE MEZZANINE'. Below the middle store is a 'STORE'. To the right of the store is a 'WC' and a 'MEETING RM'. Below the meeting room is a 'DIRECTORS OFFICE' and an 'OFFICE'. To the right of the office is a 'BOOKSHOP'. Below the bookshop is a 'SHOP'. To the right of the shop is a 'RECEPTION' area. Below the reception area are 'SCHOOLROOM 1' and 'SCHOOLROOM 2'. To the left of the main gallery is a 'VOID' and a 'STAIRS WORKSHOP AREA'. Below the workshop area is a 'STORAGE ONLY ROOM'. To the left of the storage room is a 'REAR STORE' and a 'GAS METER ROOM'. There are three lifts: 'LIFT 1' near the meeting room, 'LIFT 2' near the middle store, and 'LIFT 3' near the rear store. There are also three circulation areas: 'CIRC 1' near the meeting room, 'CIRC 2' near the middle store, and 'CIRC 3' near the rear store. A yellow box at the bottom right contains the text: 'PRESUMED ASBESTOS CONTAINING MATERIALS FOUND IN EXTERNALS'.

PRESUMED ASBESTOS CONTAINING MATERIALS FOUND IN EXTERNALS

Ⓢ This drawing is Copyright. It should not be relied on or used in circumstances other than those for which it was originally prepared and for which Cornwall County Council was originally commissioned. Cornwall County Council accepts no responsibility for this drawing to any party other than the person(s) by whom it was commissioned.

^a KEY FOR THE INTERPRETATION OF PLANTS

Presumed / possible asbestos containing materials found in room

Presumably
contains
room

	0	70-80%	character
--	---	--------	-----------

[illegible]

REV	DATE	NATURE OF REVISION
-----	------	--------------------

INTRODUCTION

[illegible]

4



COMPANY
PROFESSOR

JOHN WALL
TENNESSEE ALIEN
COUNTY COUNCIL

RICHARD FISH

**IDA, CENG, PACE, PRAKASE, PUFF
DIRECTOR**

PLANNING, TRANSPORTATION and
Construction Management Team

County Hall, 1100
Cornwall TR1 3AY

The Design and Maintenance Consultant

LOCATION

Royal Cornwall Museum

Project

Level 2

100

TYPE 2 ASBESTOS SII

0007-1226(200809)30:05;1-P

PAUL HUNTER

100

PAGE 3 OF 7

5912

PROJECT MANAGER **C Stephen**

ORIGINATOR	P. Laban
NAME	

Not to Scale

CM (continued)


75285

1000

ASBESTOS REGISTER

LEVEL 3 LAYOUT / PLAN

Royal Cornwall Museum
Level 3



PRESUMED ASBESTOS CONTAINING MATERIALS
FOUND TO EXTERIORS

© This drawing is Copyright, it should not be used or reproduced in any form without the written permission of the Cornwall Council. It is the responsibility of the user to ensure that the drawing is used in accordance with the terms of the license. The Cornwall Council does not accept any liability for any loss or damage, whether direct or indirect, arising from the use of this drawing.

SECTION INFORMATION OF PLANS

Presumed / possible asbestos
containing materials found in
room




NO	DESCRIPTION	DATE	NATURE OF REVISION
1	ORIGINAL		
2			
3			
4			
5			
6			
7			
8			
9			
10			

CORNWALL COUNCIL
RICHARD FISH
DIRECTOR
PLANNING, TRANSPORTATION AND ESTATES
County Hall, Trow
Cornwall PL1 1YU
The Design and Maintenance Consultancy

LOCATION	Royal Cornwall Museum
PROJECT	Level 2
FILE NUMBER	TYPE 2 ASBESTOS SURVEY
PAGE 4 OF 7	
PROJECT MANAGER	C. TREBERTH
SCALE	Not to Scale
DRAWING NO	75285
REVISION	R0

LEVEL 4 LAYOUT / PLAN

Royal Cornwall Museum
Level 4



PRESUMED ASBESTOS CONTAINING MATERIALS FOUND TO EXTERNALS

5 This drawing is Copyright... It should not be relied on or used in circumstances other than those for which it was originally prepared and for which Cornwall County Council was originally commissioned. Cornwall County Council accepts no responsibility for this drawing to any party other than the person(s) by whom it was commissioned.

KEY FOR THE INTERPRETATION OF PLAINS

Presumed / possible asbestos containing materials found in room

[illegible]

KEYWORDS: *depression, mood, anxiety, stress, coping, self-esteem, self-efficacy, self-esteem, self-efficacy, self-esteem, self-efficacy*



RICHARD FISH
Mkt. Gng. PACE, Pittsburg, MO
DIRECTOR
PLANNING, TRANSPORTATION AND ESTATES
County Hall, Turo
Cornwall TR1 3AY
The Design and Management Consultants

100

Royal Cornwall Museum
Level 4

TYPE 2 ASBESTOS SURVEY

ADDITIONAL INFORMATION

PAGE 5 OF 7

100

PROJECT MANAGER **C Stephen**

Signature _____ P. Lehan

10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68-69-70-71-72-73-74-75-76-77-78-79-80-81-82-83-84-85-86-87-88-89-90-91-92-93-94-95-96-97-98-99-100-101-102-103-104-105-106-107-108-109-110-111-112-113-114-115-116-117-118-119-120-121-122-123-124-125-126-127-128-129-130-131-132-133-134-135-136-137-138-139-140-141-142-143-144-145-146-147-148-149-150-151-152-153-154-155-156-157-158-159-160-161-162-163-164-165-166-167-168-169-170-171-172-173-174-175-176-177-178-179-180-181-182-183-184-185-186-187-188-189-190-191-192-193-194-195-196-197-198-199-200-201-202-203-204-205-206-207-208-209-210-211-212-213-214-215-216-217-218-219-220-221-222-223-224-225-226-227-228-229-230-231-232-233-234-235-236-237-238-239-240-241-242-243-244-245-246-247-248-249-250-251-252-253-254-255-256-257-258-259-260-261-262-263-264-265-266-267-268-269-270-271-272-273-274-275-276-277-278-279-280-281-282-283-284-285-286-287-288-289-290-291-292-293-294-295-296-297-298-299-300-301-302-303-304-305-306-307-308-309-310-311-312-313-314-315-316-317-318-319-320-321-322-323-324-325-326-327-328-329-330-331-332-333-334-335-336-337-338-339-340-341-342-343-344-345-346-347-348-349-350-351-352-353-354-355-356-357-358-359-360-361-362-363-364-365-366-367-368-369-370-371-372-373-374-375-376-377-378-379-380-381-382-383-384-385-386-387-388-389-390-391-392-393-394-395-396-397-398-399-400-401-402-403-404-405-406-407-408-409-410-411-412-413-414-415-416-417-418-419-420-421-422-423-424-425-426-427-428-429-430-431-432-433-434-435-436-437-438-439-440-441-442-443-444-445-446-447-448-449-450-451-452-453-454-455-456-457-458-459-460-461-462-463-464-465-466-467-468-469-470-471-472-473-474-475-476-477-478-479-480-481-482-483-484-485-486-487-488-489-490-491-492-493-494-495-496-497-498-499-500-501-502-503-504-505-506-507-508-509-510-511-512-513-514-515-516-517-518-519-520-521-522-523-524-525-526-527-528-529-530-531-532-533-534-535-536-537-538-539-540-541-542-543-544-545-546-547-548-549-550-551-552-553-554-555-556-557-558-559-560-561-562-563-564-565-566-567-568-569-570-571-572-573-574-575-576-577-578-579-580-581-582-583-584-585-586-587-588-589-590-591-592-593-594-595-596-597-598-599-600-601-602-603-604-605-606-607-608-609-610-611-612-613-614-615-616-617-618-619-620-621-622-623-624-625-626-627-628-629-630-631-632-633-634-635-636-637-638-639-640-641-642-643-644-645-646-647-648-649-650-651-652-653-654-655-656-657-658-659-660-661-662-663-664-665-666-667-668-669-670-671-672-673-674-675-676-677-678-679-680-681-682-683-684-685-686-687-688-689-690-691-692-693-694-695-696-697-698-699-700-701-702-703-704-705-706-707-708-709-710-711-712-713-714-715-716-717-718-719-720-721-722-723-724-725-726-727-728-729-730-731-732-733-734-735-736-737-738-739-740-741-742-743-744-745-746-747-748-749-750-751-752-753-754-755-756-757-758-759-760-761-762-763-764-765-766-767-768-769-770-771-772-773-774-775-776-777-778-779-780-781-782-783-784-785-786-787-788-789-790-791-792-793-794-795-796-797-798-799-800-801-802-803-804-805-806-807-808-809-810-811-812-813-814-815-816-817-818-819-820-821-822-823-824-825-826-827-828-829-830-831-832-833-834-835-836-837-838-839-840-841-842-843-844-845-846-847-848-849-850-851-852-853-854-855-856-857-858-859-860-861-862-863-864-865-866-867-868-869-870-871-872-873-874-875-876-877-878-879-880-881-882-883-884-885-886-887-888-889-890-891-892-893-894-895-896-897-898-899-900-901-902-903-904-905-906-907-908-909-910-911-912-913-914-915-916-917-918-919-920-921-922-923-924-925-926-927-928-929-930-931-932-933-934-935-936-937-938-939-940-941-942-943-944-945-946-947-948-949-950-951-952-953-954-955-956-957-958-959-960-961-962-963-964-965-966-967-968-969-970-971-972-973-974-975-976-977-978-979-980-981-982-983-984-985-986-987-988-989-990-991-992-993-994-995-996-997-998-999-1000-1001-1002-1003-1004-1005-1006-1007-1008-1009-1010-1011-1012-1013-1014-1015-1016-1017-1018-1019-1020-1021-1022-1023-1024-1025-1026-1027-1028-1029-1030-1031-1032-1033-1034-1035-1036-1037-1038-1039-1040-1041-1042-1043-1044


Not to Scale

Old Country

ASBESTOS REGISTER

LEVEL 5 LAYOUT / PLAN

Royal Cornwall Museum
Level 5



PRESUMED ASBESTOS CONTAINING MATERIALS
FOUND TO EXTERNALS

This drawing is Copyright. It should not be relied on or used in circumstances other than those for which it was prepared. The Royal Cornwall Museum and Cornwall County Council accept no responsibility for the drawing to any person other than the person(s) to whom it was commissioned.

1. BEFORE THE INTERPRETATION OF PLANS

Presumed / possible asbestos containing materials found in room



REV	DATE	NATURE OF REVISION
0	20/05/18	ORIGINAL

CORNWALL ASBESTOS
RICHARD FISH
DIRECTOR
PLANNING, TRANSPORTATION AND ESTATES
Cornwall Council
Cornwall, TR1 3JW
The Design and Maintenance Consultancy

LOCATION
Royal Cornwall Museum
Level 5

PROJECT
TYPE 2 ASBESTOS SURVEY

PAGE NUMBER

PAGE 6 OF 7

PROJECT MANAGER
C. CROFTON
PROJECT MANAGER
P. LEBURN
SCALE
Not to Scale

DRAWING NO
75285
REVISION
R0

ASBESTOS REGISTER

HAIRDRESSERS' SHOP LAYOUT / PLAN

Hairdressers Shop							
BACK ROOM FIRST ROOM PRESUMED ASBESTOS CONTAINING MATERIALS FOUND TO EXTERNALS							
© This drawing is Copyright. It should not be relied on or used in circumstances other than those for which it was originally prepared and for which Cornwall County Council has accepted liability. The County Council accepts no responsibility for this drawing to any party other than the person(s) to whom it was prepared.							
KEY FOR THE INTERPRETATION OF PLANS ☐ Presumed / possible asbestos containing materials found in room							
<table><tr><td>REV</td><td>DATE</td><td>NATURE OF REVISION</td></tr><tr><td>0</td><td>20/05/18</td><td>ORIGINAL</td></tr></table>		REV	DATE	NATURE OF REVISION	0	20/05/18	ORIGINAL
REV	DATE	NATURE OF REVISION					
0	20/05/18	ORIGINAL					
PREPARED BY							
CORNWALL COUNTY COUNCIL RICHARD FISH Planning, Transportation and Estates Cornwall TPL 347 Cornwall TPL 347 The Design and Administration Unit							
LOCATION Hairdressers Shop							
PROJECT TYPE 2 ASBESTOS SURVEY							
PAGE NUMBER PAGE 7 OF 7							
PROJECT MANAGER C. STEPHEN							
DESIGNER P. LEBEL							
SCALE Not to Scale							
DRAWING NO. 75285							
REVISION R0							

HEALTH AND SAFETY POLICY REVIEWS

POLICY REVIEWS

Date	Summary / comments	Verified by:

Review of the health and safety policy statement

It is the policy of the employer to review this written policy statement ***annually***.

HEALTH AND SAFETY POLICY REVIEWS

TABLE OF AMENDMENTS ARISING FROM REVIEWS

Date	Amendment	Remarks
11/10/12	SAMPLE TAKEN FROM PATCH PANEL ROOM PROULD TO BE NEGATIVE	CORRECT REPORT 11/10/12 APPENDED



Engineering Services Laboratory
Radnor Road, Scorrier, Redruth TR16 5EH TEL : 01872 327381 FAX : 01209 821539

ASBESTOS BULK SAMPLE ANALYSIS TEST REPORT



In House Method based on HSG248

Scheme / Site: **Bulk Sample Analysis**

Location: **Unknown**

Date Sampled: **11/10/2012**

Sampled By: **CLT**

Date Received: **11/10/2012**

Date Tested: **11/10/2012**

Tested By: **EB**

Test Report No: **AS6744.1**

Project No: **76647**

Client Ref: **-**

Sample Cert No: **AS 5436**

Date Reported: **12/10/2012**

Page Number: **1 of 1**

Test Results

Sub Sample Number	Client Sample Number	Sample Type	Sample Details	Asbestos Type(s) Present
1	-	IB	Panel in cupboard	AND

For additional information see the Sampling Certificate.

KEY:

Sample Type: A = Adhesive, C = Cement, D = Dust/Debris, FB = Fibre Board, G = Gasket, IB = Insulating Board, I = Insulation, L = Lagging, PL = Pipe Lagging, R = Resin, RF = Roof Felt, SP = Sink Pad, SC = Spray Coating, P = Paper, TC = Textured Coating, T = Textile, VFT = Vinyl Floor Tile, VFC = Vinyl Floor Covering, W = Wood, O = Other (detailed).

Asbestos Type: AM = Amosite, CH = Chrysotile, CR = Crocidolite, Trem = Fibrous Tremolite, Actin = Fibrous Actinolite, Anth = Fibrous Anthophyllite, AND = Asbestos Not Detected.

Remarks : Materials have been referred to as Asbestos Insulating Board or Asbestos Cement based on upon their asbestos content and visual appearance alone. Water absorbency checks on materials have not been carried out unless stated otherwise. Where this has been done, the test is outside the scope of UKAS Accreditation. Where samples have not been taken by Engineering Services Laboratory, it can only report analysis results. No responsibility can be taken for any consequences arising from the client's sampling strategy or procedures, or the use of these results in subsequent reports.

Client Name: **Safety Cornwall**
F.A.O: **Terry Pike**
Address: **6 Glenthorne House**
Truro Industrial Park
Threemilestone

Truro
TR3 6BW
Tel No: 01872 242207 Fax No:

Authorised Signatory:

Paul Laban – Geoenvironmental Engineer

T:\test\2012\10\12\MAINLMS-AS6744-1-crowe-094443-0.DOC : Revision 18, Date: 26/11/2008, By: RNH.

This Report relates only to the samples tested.

Opinions and interpretations expressed herein, or any water absorption tests performed, are outside the scope of UKAS accreditation.

This report may not be reproduced except in full, without the written approval of the Laboratory.

