

PHOTO 1 - EXTENT OF PHASE 1 WORKS SHADED YELLOW





PHOTO 2 - NORTH CONCEALED VALLEY GUTTER





PHOTO 3 - WEST ELEVATION ROOF OVER REGISTRAR'S OFFICE





PHOTO 4 - WEST ELEVATION EXTENT OF WORKS IN YELLOW





PHOTO 5 - SWEPT VALLEY TO WEST ELEVATION GABLE AND DORMER. NOTE ALSO ROOF TO ORIEL WINDOW.





PHOTO 6 - COUNCIL CHAMBER ROOF AND CHIMNEY.  
NOTE: CONCEALED STUB GABLE TO BUSINESS SUITE TO REAR





PHOTO 7 - ROOF TO COUNCIL CHAMBER BAY WINDOW





PHOTO 8 - CONCEALED VALLEY GUTTERS OVER MAIN STAIRCASE TO BE REPLACED.





PHOTO 9 - CONCEALED VALLEY AND INNER ROOF SLOPE OVER MAIN STAIRCASE TO BE REPLACED AND RE-TILED RESPECTIVELY





PHOTO 10 - EAST ELEVATION OF COUNCIL CHAMBER AND BAY WINDOW





PHOTO 11 - WEST ELEVATION REGISTRAR'S OFFICE WINDOW





PHOTO 12 - COUNCIL CHAMBER ORIEL WINDOW ROOF





PHOTO 13 - CITIZEN'S ADVICE BUREAU ENTRANCE WITH REGISTRAR'S OFFICE OVER





PHOTO 14 - CCTV ON EAVES TO BE RELOCATED, PROTECTED, MAINTAINED DURING THE WORKS.

