




DISS CEMETERY
CHAPELS

NOT TO SCALE
JUNE 1980 TRN.







1. Centre East



2. East South End




3. South







5. West Centre




6. West North End



7. North



8. East North End




11. Inner wall plate curvature south face to workshop



12. Typical valley detail



13. Typical slipped/replacement tiles and mortar flaunching to gable



14. Chapel roof