



European Union
European Regional
Development Fund



HM Government



Craigshill Wood Gauging Station Photo Record

Pre-works/ Baseline Photos



Photo 1: View upstream from right hand bank of Craigshill Wood gauging station in low flows.



Photo 2: View downstream from right hand bank of Craigshill Wood gauging station in low flows.



European Union
European Regional
Development Fund



HM Government



Craigshill Wood Gauging Station Photo Record



Photo 3: View of structure and downstream pre barrage and eel pass in low flows.



Photo 4: View of structure and downstream pre barrage and eel pass in elevated flows.



European Union
European Regional
Development Fund



HM Government



Craigshill Wood Gauging Station Photo Record



Picture 5: View of central low flow channel looking downstream.



Picture 6: View of gauging section upstream of structure in low flows.

Craigshill Wood Gauging Station Photo Record



Picture 7a and 7b: Eel cassette pass attached to right hand side wingwall of Craigshill Wood gauging station.



Picture 8a and 8b: Removed eel cassette to show internal tile and bristle formation



European Union
European Regional
Development Fund



HM Government



Craigshill Wood Gauging Station Photo Record



Picture 9: Road adjacent to structure on left hand bank which leads to forestry access gate.



Picture 10: Gate part way down the road which leads to a forestry track and grants access to the work site.

Craigshill Wood Gauging Station Photo Record



Picture 11: Start of forestry track (beyond gate) which leads directly to Craigshill Wood gauging station.



Picture 12: End of forestry track which leads to gauging hut and lay down area.



European Union
European Regional
Development Fund



HM Government



Craigshill Wood Gauging Station Photo Record



Photo 13: Extent of lay down area which slopes slightly.



Photo 14: Drop off of lay down area next to gauging hut.