



KEY	
	EXISTING DEFECTS
	Longitudinal Crack
	Crazing
	Rut
	Loops
	Core Sample Position
	Pothole
	Surface Change
	Open Joint
	Photo Reference

highways england

PROJECT: M5 J10-9 NB MP 76.8-69.5

STATUS: DRAWING NUMBER: 001

DRAWING NUMBER: 001

Sheet 1 of 6

Rev	By	Date	Notes
A	JCM	10/02/2020	Final Issue - VM

REFER TO SHEET 2 OF 6